MASE



252 W. Adams, P.O. Box 399 • Morton, Illinois 61550-0399

Job: Date: Page: B044047808

2/19/2015 1 of 9

Construction Proposal

Chuck Sinkle 1451 17th Rd.

Home, Kansas 66438 Home: 785-799-3716 Cell: 785-799-7593

Work: Other:



Chuck Sinkie 1451 17th Rd.

Home, Kansas 66438 Home: 785-799-3716 Cell: 785-799-7593

Work: Other:

ng Info	Style	Width	Height	Length	Truss Spacing	Roof Pitch	Lower Chord Pitch
	172	36'	12'	48'	12'	4/12	0/12

172 36'x12'x48' (#1) - Building Use: Farm - Storage

Pricing is based on cash terms according to the payment schedule shown. Non-cash payments are subject to Terms and Conditions. #2. All applicable taxes are included in the total price.

Pricing is contingent upon delivery of material on or before July 31, 2015. (See Building Site Specifications, #2)

Down Payment:

Delivery Payment:

Final Payment:

Total:

\$9,920.00

\$19,840.00

\$3,307.00

\$33,067.00

Approximate delivery after May 04, 2015.

Down payment type: Check # 1/398

THIS ORDER CONSISTS OF BUILDING SPECIFICATION(S), BUILDING PERSPECTIVE(S). COLUMN PLAN(S), BUILDING COLOR DEFINITION(S), SITE CONDITIONS BUILDING SITE SPECIFICATIONS (06/10), TERMS AND CONDITIONS (06/10), CONSTRUCTION PLANNING WARNING (06/10), AND 613 FLUOROFLEX® LIMITED WARRANTY WHICH ARE ATTACHED AND **INCORPORATED HEREIN**

By signature below, I certify that

HUCK (Print Property Owner's Name)

_ hold(s) title to the

property upon which construction will be performed under this Order and has given permission for construction

Signature of Chuck Sinkie

2-/9- /5 Signature Date

Job: Date:

Page:

B044047808

2/19/2015 2 of 9

252 W. Adams, P.O. Box 399 • Morton, Illinois 61550-0399

Building #1 Specifications

172 36' 12' 48' 12' 4/12 0/12	Style	Width	Height	Length	Truss Spacing	Roof Pitch	Lower Chord Pitch
17/4 10/12	172	36'	12'	48'	12'	4/12	0/12

172 36'x12'x48' (#1) - Building Use: Farm - Storage

Foundation

Morton Buildings, Inc. exclusive foundation system. Reinforced precast concrete column with an internal threaded adjustment bracket set in a readi-mix poured footing set below frost depth or a minimum of 4'-0" below building grade. Fastened to a laminated wood column with an internal column connector bracket.

Siding

West, South, East, North wall(s) Fluoroflex™ 1000 Hi-Rib Steel Minimum .019 (Fastened with Stainless Steel Screws) without wainscot

Protective Liner

West, South, East, North wall(s) with 7/16" OSB Protective Liner

Roof

1

Fluoroflex™ 1000 Hi-Rib Steel Minimum .019 (Fastened with Stainless Steel Screws) with Formed Dry-Panel

2'6" Square Cupola, Functional without a fan with 'M' 30" Weathervane

Overhangs

West, East wall(s) 1' Wide Non Vented Sidewall Overhang with Standard 6" fascia, Gutters, downspouts with elbows at base South, North wall(s) 1' Wide Non Vented Endwall Overhang with Standard 6" fascia

Walk Doors

Α

3' x 6'8" MB 910 9 Lite Tempered Glass in Leaf with Embossed Crossbuck Walk Door(s) in swing left hinge with lockset

Sliding Doors

В 16' X 12' Double Alumasteel Sliding Door(s)(slide both directions) with Protective Liner

Dutch Doors

4' x 7'2" Dutch Door, Right Hinge С

Skylights

(Approx. 3' x 6'5") full skylight(s)

Additional Information

Note:

East side wall will be OPEN 24' from the North corner. Open 12' high--Covered with metal trim--White.

MBSP



252 W. Adams, P.O. Box 399 • Morton, Illinois 61550-0399

Job: Date: Page:

2/19/2015

2/19/2015 3 of 9

B044047808

Disclaimers

Sliding door panels which cannot be secured are not covered by Morton's wind warranty.

Sliding door openings will be 4 1/2" to 7 1/2" less in width (except sliding doors located in sidewall and endwall corner may be up to 11 1/4" less in width) than door panels and opening height will be reduced by thickness of concrete floor if concrete is installed.

Customer relieves Morton Buildings, Inc. from liability for snow infiltration which may occur under certain conditions including but not limited to high wind, snow level and building orientation.



Job: Date: Page: B044047808

2/19/2015 4 of 9

Building 172 36'x12'x48' (#1) Perspective From The Northwest

Peak Height 19'3"
Soffit Height 13'3.5"
Grade to Heel 12'
Roof Pitch 4/12




Job: Date:

Page:

B044047808

2/19/2015 5 of 9

Building 172 36'x12'x48' (#1) Perspective From The Southeast






Job: Date: Page: B044047808

2/19/2015 6 of 9

172 36'x12'x48' (#1) Column Plan






Job: Date: Page: B044047808

2/19/2015 7 of 9

Building 172 36'x12'x48' (#1) Color Definition



Roof HiRib Steel Ridgecap Soffit Gable (Roof) Fascla Gutter	Color Charcoal Charcoal White Charcoal White White	Cupola Roof Sides Base Walk Doors	Color Charcoal White Charcoal
Side & End Wall HiRib Steel Downspouts Comer Trim Base Trim	Color White White White White	Walkdoor No Crossbuck (Fibersteel & MB) Walkdoor with Crossbuck (Fibersteel & MB) Dutch Doors Crossbuck Trim Insert	White White Color Red * White White
Sliding Door HiRib Steel Vertical Rails Track Cover Jamb End Door Top	Color White Red Red White Red		

Note: Items marked with an asterisk (*) include a setup charge.

Note: The photograph above is an approximation of the features and colors on the Morton building reflected in this order and may not accurately depict the actual features and colors applied to the building.

This building will not be connected to another building and no other Morton building is on site.

CLS



Job: Date: B044047808

Page:

2/19/2015 8 of 9

Site Work Responsibilities

Morton Buildings, Inc. has prepared Building Site Specifications with Diagrams and made them part of this agreement. The checklist below designates whether Morton (MBI) or Owner (O) is responsible to perform and pay for the services identified.

Concrete
(Owner) Poured Foundation/Wall (see scope of work)
(Owner) Floor/Interior(Flatwork)
(Owner) Concrete Flatwork Preparation
(Owner) Door Approach/Exterior
(Owner) Sidewalks
Cheuter
Utilities
(Owner) Temporary Electrical Service
(Owner) Permanent Electrical rough-in/hookup
(Owner) Gas Service rough-in/hookup
(Owner) Water Service rough-in/hookup
(Owner) Sewer Service rough-in/hookup
(Owner) Cable TV Service rough-in/hookup
(Owner) Internet Service rough-in/hookup
Applicable Inspections
(Owner) Termite
(Owner) Footing
(Owner) Framing
(Owner) Electrical Rough
(Owner) Electrical Finish
(Owner) Plumbing Rough
(Owner) Plumbing Finish
(Owner) HVAC/Mechanical Rough
(Owner) HVAC/Mechanical Finish
(Owner) Fire/Life Safety
(Owner) Final
(Owner) Certificate of Occupancy

Site Conditions

The building site was inspected on 1/30/2015 by: Darrel, Chuck, 14NUE

Attach a photograph of site taken on above date and describe site preparation which must take place before delivery of material: customer

Define Benchmark Location: NW corner

